

Abstract

Confidence levels on a probability distribution are analyzed based on data sets of varying size. Using a curve such as a Weibull distribution curve, computations can be made such as the odds that a percentage of a plurality of parts will fail after a

5 prescribed time.

T09090"154.10001